



PERSONNEL QUALIFICATIONS

Ralf Leistikow | Principal



EDUCATION

- Georgia Institute of Technology
 - Bachelor of Science, Civil Engineering, 1986
 - Master of Science, Civil Engineering, 1988

PRACTICE AREAS

- Collapse Investigation
- Disaster Response
- Materials Investigation
- Parking Structures
- Prestressed and Post-Tensioning
- Repair and Rehabilitation Design
- Structural Investigation
- Testing and Instrumentation

REGISTRATIONS

- Professional Engineer in AL, FL, GA, MS, NC, SC, and VA
- Structural Engineer in GA

PROFESSIONAL AFFILIATIONS

- American Concrete Institute (ACI)
- American Society of Civil Engineers (ASCE)
- International Concrete Repair Institute (ICRI) - Georgia Chapter, past president
- Post-Tensioning Institute (PCI)

TECHNICAL COMMITTEES

- ACI 224 - Cracking of Concrete

CONTACT

rleistikow@wje.com
984.345.0630
www.wje.com

EXPERIENCE

Since joining WJE in 1991, Ralf Leistikow has been involved in numerous structural investigations, condition surveys, analyses, and repair designs on low- and high-rise buildings, as well as parking, commercial, and underground structures throughout the U.S. Southeast and U.S. East Coast. His work includes the evaluation of post-tensioned, precast, and conventionally reinforced concrete structures; cast-in-place pavements and industrial floors; retaining walls and wood-framed and light-gauge, metal-framed structures; structural steel-framed structures; and pre-engineered buildings. Mr. Leistikow has also investigated building envelopes consisting of precast, brick masonry, stone, stucco, EIFS, and various curtain wall systems.

Mr. Leistikow participates in and leads the investigation of structural damage and deterioration related to excessive loadings, deflections, deficient construction materials, moisture infiltration, corrosion, and fire. He has also led various failure investigations involving temporary falsework and suspended scaffolding systems. Mr. Leistikow performs assessments of alleged tornado and hurricane damage, conducts prepurchase assessments, and provides litigation support for various types of projects and clients.

REPRESENTATIVE PROJECTS

Collapse Investigation

- Partial Roof Collapse - Charlotte, NC: Evaluation of precast roof framing and falsework
- Atlanta Botanical Gardens Canopy Walkway - GA: Investigation of partially collapsed steel pedestrian bridge structure and temporary falsework
- Mansell Road Office Building - Alpharetta, GA: Investigation of collapse of steel frame and composite slab
- Orme Street Trunk Combined Sewer - Atlanta, GA: Investigation of unreinforced concrete tunnel

Disaster Response

- Fire Damage Assessment - AL, FL, GA, LA, and NC: Field investigation and analysis of multiple fire-damaged structural steel, wood, and concrete structures
- Hurricane and Tornado Damage Assessments - U.S. Atlantic and Gulf Coasts: Field investigation and analysis of wind and surge-related damage on multiple commercial, government, and residential projects following 1995 to more recently named hurricanes

Parking Structures

- Midtown Green - Raleigh, NC: Assessment of post-tensioned stressing end anchors
- Georgia Institute of Technology, North Campus Parking Deck - Atlanta: Evaluation and development of repair procedures for cracked columns and other construction defects
- Knoxville City and Knox County Building - TN: Investigation, long-term acoustic monitoring, and repair of post-tensioned parking structure

Repair and Rehabilitation Design

- Quorum Center - Raleigh, NC: Concrete column fire damage assessment, testing, analysis, and repair design
- Lowe's Motor Speedway - Concord, NC: Condition survey, load testing, and retrofit design
- Hilton Garden Inn at Sugarloaf - Duluth, GA: Condition survey and repair design of hollow core plank floor and concrete unit masonry wall systems following excessive differential building settlement

Structural Investigation

- Solar Field - Lumberton, NC: Assessment of alleged wind damage to solar panel support framing system
- U-Pointe Apartments - Kennesaw, GA: Assessment and structural analysis of plate connected wood truss failures
- Fox Theatre - Atlanta, GA: Condition survey of balcony and vibration study
- Snellville Billboards - Snellville, GA: Evaluation of billboard framing
- Transmission Towers - GA: Concrete foundation distress investigation