



## PERSONNEL QUALIFICATIONS

### Jennifer Schneider | Associate III



#### EDUCATION

- University of Illinois at Urbana-Champaign
  - Bachelor of Science in Architectural Design, 2007
  - Master of Architecture, Structures Option, 2009

#### PRACTICE AREAS

- Building Enclosure Commissioning
- Facade Assessment
- Repair and Rehabilitation
- Water/Air Leakage Assessment
- Windows and Curtain Walls
- Historic Preservation

#### REGISTRATIONS

- Architect in IL
- LEED Accredited Professional

#### PROFESSIONAL AFFILIATIONS

- Building Enclosure Council - Chicago

#### CONTACT

jschneider@wje.com  
312.372.0555  
www.wje.com

#### EXPERIENCE

Since joining WJE in 2009, Jennifer Schneider has been involved with numerous projects related to the inspection, investigation, and repair of distressed conditions in existing buildings. Her responsibilities include inspections of existing buildings and structures, report writing, design repairs, developing construction documents, and providing field observation services for repair work during the construction phase. Ms. Schneider performs evaluations of brick, terra cotta, stone, concrete, and glass facades. She also performs hygrothermal analyses and condensation investigations of various building systems.

#### REPRESENTATIVE PROJECTS

##### Building Enclosure Commissioning

- Argonne National Laboratory, Energy Sciences Building - Lemont, IL: 150,000 square-foot office and laboratory building with metal panel rain screen cladding, aluminum and glass curtain wall facade

##### Facade Assessment

- 1769, 1819, and 1869 West Pershing Road - Chicago, IL: Brick masonry and terra cotta facade inspection; report and repair program
- Soho House - Chicago, IL: Brick masonry facade assessment and repair recommendations
- Millennium Park, Crown Fountain - Chicago, IL: Evaluation of damaged glass brick at glass-clad structure
- University of Wisconsin-Madison, Student Center: Evaluation of roof membrane using holiday detector
- Mercy Hospital - Ardmore, OK: Building envelope assessment using monitoring devices; construction period services for repair of air barrier defects in a masonry and metal panel facade

##### Repair and Rehabilitation

- 112 South Michigan Avenue, Chicago, IL: Construction documents and construction period services for concrete and masonry repair
- Petersen Family Wellness Center - Harlan, IA: Metal building exterior wall repairs and construction period services to address condensation in a natatorium
- Macy's - IL: Brick and limestone facade repairs for multiple locations
- Gold Coast Galleria - Chicago, IL: Construction period services for repair of concrete and window wall facade
- 3600 North Lake Shore Drive - Chicago, IL: Construction period services for repair of concrete and masonry facade

##### Water/Air Leakage Assessment

- Buffalo Federal Courthouse - Buffalo, NY: Evaluation of condensation potential in exterior wall
- SoNo Condominiums - Chicago, IL: Water leakage investigation at high-rise condominium
- Michigan-Indiana Townhomes - Chicago, IL: Water leakage investigation at residential community

##### Windows and Curtain Walls

- Daley Center - Chicago, IL: Thermal analysis to improve the performance of a historic window wall
- 400 East Randolph - Chicago, IL: Aluminum window replacement at high-rise condominium
- 11 South LaSalle Street - Chicago, IL: Aluminum window replacement at historic hotel

##### Historic Preservation

- Eisenhower Executive Office Building - Washington, D.C.: Onsite historic preservation specialist for interior renovation; preparation of measured HABS drawings
- 39 South LaSalle - Chicago, IL: Facade repair of 1890s terra cotta facade